RETURN TO TECHNICAL SERVICE BULLETIN TABLE OF CONTENTS
RETURN TO CD-ROM TABLE OF CONTENTS

NARKOMED 6000
TECHNICAL SERVICE BULLETIN # 6014

Product: Narkomed 6000

Date: March 6, 2001

Re: Support of WPU replacements for Narkomed 6000's configured with 3.01 application version software.

Reference Doc: ECR # 02-0008 - Release 3.01 Software and related PD docs.

Reason/Rational: All Service Exchange (SE) Workstation Processor Units (WPU) are shipped with application software version 2.06. If a failed WPU was at version 3.01 as identified by a label near the serial number tag the installed WPU must be loaded with 3.01 software at the customer site.

Solution/ Procedure: Refer to installation instructions provided in Field Service Procedure SP00236 Narkomed 6000 3.01 Enhancement

Devices affected: All units starting at S/N 11073 and higher. All machines fitted with an Integrated Patient Monitoring Module (IPMM). All other units identified by a 3.01 label near its serial number label.

DrägerService
3122 Commerce Drive
Telford, PA 18969
Tel: (215) 721-5402
(800) 543-5047
Fax: (215) 721-5784
Web: www.draegermed.com
DrägerService is a division of
Draeger Medical

Timing/When: This update shall be performed on included devices during Service Calls requiring the replacement of WPU.

Additional Info:

Costs: If you are the service provider of a machine serial number that is at software version 3.01 the software required to support the product is available at no charge if this TSB is referenced at the time the order is being placed.

Ordering Info/Parts: 1 ea. *4115420-003 CD-ROM NM6000 SOFTWARE-V3.01
* Maximum order quantity 1 CD-ROM per Technician

Distribution: Draeger Medical Inc. USA – Service; Education, Customer Service, Affected DMI Distributors and Qualified Service Organizations.

If you have any questions, please contact Technical Support by phone at 1-800-543-5047, by fax at 1-215-721-5789 or by E-mail at techsupport@draegermed.com